

Quick Card

T-BERD®/MTS-2000 Modular Test Set

StrataSync™

This procedure describes how to synchronize the T-BERD/MTS-2000 or SmartOTDR to the **StrataSync** cloud-based Asset Management System. Syncing requires internet connectivity from the test set. The T-BERD/MTS-2000 includes an internal Ethernet port, USB port for tethering, and optional Wi-Fi. SmartOTDR supports USB Tethering and optional Wi-Fi.

Equipment Requirements:

- T-BERD/MTS-2000 or SmartOTDR equipped with the following:
 - Software Release V16.22 or greater
 - Wireless option for Wi-Fi Connectivity
- Internet connection (via Ethernet, Wi-Fi, or USB Tether)

The following information is required to complete the procedure:

- StrataSync Account ID
- StrataSync Tech ID





Press the **ON/OFF** button to turn on the T-BERD/MTS-2000 or SmartOTDR.



Press the HOME button to display the Home Screen.



Tap the Connectivity icon to view the Connectivity Screen.



Establish a connection to the internet from the Ethernet or Wireless Configuration screens, then tap the **Exit** soft key to return to the **Connectivity Screen.**



Tap the **StrataSync** icon in the **Connectivity Screen** to view StrataSync settings.




Figure 1: Home Screen



Figure 2: Connectivity Screen








Figure 3: StrataSync Settings Screen

- 6. Configure the StrataSync settings:
 - Server Type:
 - Select Viavi Server if you are using VIAVI's secure cloud-based server.
 - If your company has it's own StrataSync server, select Server Address and type in the server address.
 - Account ID:
 - o Press the right arrow key on the T-BERD/MTS to display the keyboard.
 - o Enter your StrataSync Account Number.
 - Technician ID:
 - Press the right arrow key on the T-BERD/MTS to display the keyboard.
 - Enter your StrataSync Tech ID.
 - **Upload From:** This is the OTDR folder which will be synchronized with StrataSync. You can change it to any available folder on the test set.
 - o To change the folder, press the **FILE** hard key and highlight the desired folder.
 - Note that only files that have not been uploaded will be uploaded. Only files in that one folder will be uploaded.
- 7. Once all configurations are set, tap the **Connect to StrataSync** soft key on the top right of the display. A **Cloud** icon will appear in the **Status Bar** on the top screen. As soon as it disappears and the **Connect to StrataSync** soft key becomes available, your sync process is finished.
- 8. After your StrataSync connection has been configured and activated for the first time, you can also sync your unit directly from the **Home Screen** by tapping the **StrataSync** icon.



Accessing your Stratasync Account via WEB Browser:

1. Open your web browser, go to: http://stratasync.viavisolutions.com, and enter your User Name and Password to login to your StrataSync Account




Figure 4: StataSync Login

2. Click on the Test Data menu and select the Test Data List. To find your results, you can either look for your **Tech ID** or search for this specific instrument in the **Asset Type**.




Figure 5: Test Data menu

3. To download test data to your PC, right-click on the desired report and click Download. Note: To save multiple reports, use the Actions drop-down menu to Check All on this Page, Check **All on All pages**, or **Download**. A zip file with the selected reports will download to your browser.




Figure 6: Downloading test data